

### Fleece bands

- For grinding, cleaning and finishing work. For removing scratches, colour runs and oxide layers.
- For preparing, pre-grinding and polishing weld seams
- Recommended circumferential speed: 25-30 m/s for steel
- Recommended circumferential speed: 15-25 m/s for stainless steel
- Recommended circumferential speed: 30-40 m/s for soft NF metals
- Recommended circumferential speed: 5-15 m/s for high temperature Ni-/ Co alloys



Representative picture

Dimensions	Grit	Sales unit	Order No.
6 x 457 mm // 1/4 x 18 3/4 "	coarse	5	626383000
6 x 457 mm // 1/4 x 18 3/4 "	medium	5	626384000
6 x 457 mm // 1/4 x 18 3/4 "	very fine	5	626386000
13 x 457 mm // 1/2 x 18 3/4 "	coarse	5	626387000
13 x 457 mm // 1/2 x 18 3/4 "	medium	5	626388000
13 x 457 mm // 1/2 x 18 3/4 "	very fine	5	626390000
19 x 457 mm // 3/4 x 18 3/4 "	coarse	5	626391000
19 x 457 mm // 3/4 x 18 3/4 "	medium	5	626392000
19 x 457 mm // 3/4 x 18 3/4 "	very fine	5	626394000